

10.

8.0

4.0

8.0 + 4

6.0

10.0

5.0

30.0

2.0 - 4.0 + 2

8.0

4.0 - 8.0 + 4

4.0

5.0 - 6.0 + 1

24.0

5.0

8.0

5.0

3.0

7.0

10.0

11.0

7.0

10.0

10.0

10.0

16.0

1227.0

238 man for 10 units shop

100 hour for 10 unit shop

~~225~~ hours~~225~~ hours labor100⁰⁰ parts labor20⁰⁰ parts materials

300/0

500/0

227
2382123
3675

28

This document is part of an integrated file. If separated from the file it must be subjected to individual cyclical review.

10220
272
8220
3602.7
81238
36

36

AUTOMATIC KEYER

TIME + MATEL ESTIMATE FOR 10 + 50 UNITS

BARS, FRAME, BASE 2 REQD./UNIT.

BLANK SIZE = $\frac{1}{4} \times \frac{3}{8}$ C.R. STL. STOCK X $12\frac{1}{2}$ " LONG.

TIME { 10 UNITS MACHINING AND BENCH TIME = 18.0 HRS.
 { 50 UNITS " " " " " = 35.0 HRS.

BARS, FRAME, TOP

2 REQD/UNIT

BLANK SIZE = SAME AS ABOVE.

MATL. { 10 UNITS REQUIRES 21 FT = \$.
50 " " 105 FT . \$

TIME { 10 UNITS MACHINING AND BENCH TIME = 8.0 HRS.
 { 50 UNITS " " " " " : 34.0 HRS.

BOARD, CHASSIS

1 REQD. / UNIT

LOU. FLOOR **BLANK SIZE = 12 7/16 x 5 7/8 x 1/16 THICK COPPER CLAD APOXY GLASS.**
 MATL. { 10 UNITS REQUIRE $750 \text{ sq. in.} = \$ \frac{\text{--}}{\text{--}}$
 { 50 UNITS " $3750 \text{ sq. in.} = \$ \frac{\text{--}}{\text{--}}$.
 TIME { 10 UNITS CUTTING TO SIZE + DR. ALL HOLES = 6 HRS.
 { 50 UNITS " " " " " " : 30 HRS

BOARDS, PLUG IN (B-1, B-2, B-3, B-4, B-5, POWER SUPPLY)

Math is figured by L. Flahr & H. Salmon.

$$\text{TIME} \left\{ \begin{array}{l} 10 \text{ UNITS CUT TO SIZE + DR. HOLES} = 10 \text{ HRS} \\ 50 \text{ UNITS " " " " " } = 50 \text{ HRS} \end{array} \right.$$

SCREWS AND NUTS FOR 10 UNITS = ?

“*It is the same with us, we are not the same as we were, we are not the same as we are.*”

50 UNITS : ?

This document is part of an integrated file. If separated from the file it must be subjected to individual systematic review.

SPRINGS 2ER UNIT

5.0
0.0

#2

COVER, FRONT + BACK 1 REQD EACH/UNIT TOTAL 20 COVERS
BLANK SIZE = $7\frac{1}{4} \times 5\frac{3}{16} \times 0.048$ C.R. STL. + 100 COVERS

MATL { 10 UNITS REQUIRES 752 sq. in. = \$
50 UNITS " 3760 sq. in. = \$
TIME { 10 UNITS, TOTAL SHOP TIME = 30 HRS.
50 UNITS " " " = 150 HRS.

COVER, CHASSIS 1 REQD/UNIT

BLANK SIZE: $11 \times 13\frac{3}{4} \times 0.038$ PERFORATED C.R. STL.

MATL { 10 UNITS REQUIRES 152 sq. in. = \$
50 UNITS " 760 sq. in. = \$
TIME { 10 UNITS TOTAL SHOP TIME = 4.0 HRS.
50 UNITS " " " = 20.0 HRS.

ARM 2 REQD/UNIT

BLANK SIZE = $1\frac{3}{4} \times \frac{3}{8} \times \frac{1}{4}$ FABRIC PHENOLIC

MATL { 10 UNITS REQUIRES 7.50 sq. in of $\frac{1}{4}$ " MATL = \$
50 UNITS " 37.50 sq. in of $\frac{1}{4}$ " MATL = \$
TIME { 10 UNITS TOTAL SHOP TIME = 8.0 HRS.
50 UNITS " " " = 40.0 HRS.

PLATE, MOUNTING 1 REQD/UNIT

BLANK SIZE = $3\frac{7}{16} \times 3\frac{1}{16} \times 0.048$ C.R. STL.

MATL { 10 UNITS REQUIRES 105.3 sq. in = \$
50 UNITS " 526.5 sq. in = \$
TIME { 10 UNITS TOTAL SHOP TIME = 8.0 HRS.
50 UNITS " " " = 40.0 HRS.

#3

SPACER, TRANSFORMER 4 REQD/UNIT

SPACER, TRANS FORMER BRACKET 2 REQD/UNIT

BLANK SIZE : $\frac{3}{8}$ " DIA. ROD X $\frac{7}{16}$ LONG FABRIC PHENOLIC.

MATL { 10 UNITS REQUIRES 30 in of $\frac{3}{8}$ DIA ROD.
50 UNITS " 150 in of $\frac{3}{8}$ DIA ROD.

$$\text{TIME } \left\{ \begin{array}{lll} 10 \text{ UNITS} & \text{TOTAL SHOP TIME} & = 4.0 \text{ HRS} \\ 50 \text{ UNITS} & " & = 20.0 \text{ HRS} \end{array} \right.$$

1 KNO8 / REQD/UNIT

BLANK SIZE = $5/8$ DIA X $7/8$ LONG ALUMINUM ROD.

MATL { 10 UNITS REQUIRES 9 in = \$.
50 UNITS " 45 in = \$

$$\text{TIME} \left\{ \begin{array}{lll} 10 \text{ UNITS} & \text{TOTAL SHOP TIME} = 6.0 \text{ HRS} \\ 50 \text{ UNITS} & " & " & " & = 25.0 \text{ HRS} \end{array} \right.$$

PLATE, MOUNTING 1 REQD/UNIT

BLANK SIZE = 2 5/8 X 2 1/8 X 3/8 THICK FABRIC PHENOLIC.

$$\text{MATERIAL} \left\{ \begin{array}{l} 10 \text{ UNITS} \text{ REQUIRES } 40 \text{ sq. in.} = \$ \\ 50 \text{ UNITS} \quad " \quad 200 \text{ sq. in.} = \$ \end{array} \right.$$

$$\text{TIME} \left\{ \begin{array}{l} 10 \text{ UNITS} \quad \text{TOTAL SHOP TIME} = 24.0 \text{ HRS} \\ 50 \text{ UNITS} \quad " \quad " \quad " \quad = 120.0 \text{ HRS} \end{array} \right.$$

PLATE, BOTTOM 1 REQD/UNIT

BLANK SIZE = 11 X 5 1/16 X 1/16 THICK FABRIC PHENOLIC.

MATL { 10 UNITS REQUIRES 5.0 mg. ft. = \$. . .
 { 50 UNITS " 25.0 mg. ft. = \$. . .

$$\text{TIME} \left\{ \begin{array}{l} 10 \text{ UNITS} \quad \text{TOTAL SHOP TIME} = 5.0 \text{ HRS} \\ 50 \text{ UNITS} \quad " \quad " \quad " \quad " \quad = 25.0 \text{ HRS} \end{array} \right.$$

PADDLE (#1 + #2) 1 EACH REQD/UNIT

BLANK SIZE = $3\frac{1}{8} \times 1\frac{1}{4} \times \frac{1}{8}$ THICK BLACK ^{FABRIC} PHENOLIC

MAT'L { 10 UNITS REQUIRES 80.0 sq. in. = \$
 50 UNITS " 400.0 sq. in. = \$

TIME { 10 UNITS TOTAL SHOP TIME = 8.0 HRS.
 50 UNITS " " " = 40.0 HRS.

CONTACT 2 EA REQD/UNIT

BLANK SIZE: $\frac{1}{8}$ DIA X $\frac{1}{4}$ LONG COIN SILVER

MAT'L { 10 UNITS REQUIRES 5 in. = \$
 50 UNITS " 25 in. = \$

TIME { 10 UNITS TOTAL SHOP TIME = 5.0 HRS.
 50 UNITS " " " = 25.0 HRS.

CONTACT STRIP REACH REQD/UNIT

BLANK SIZE: $1\frac{3}{4} \times \frac{1}{4} \times .006$ THICK PHOSPHOR BRONZE

MAT'L { 10 UNITS REQUIRES 5 sq. in. = \$
 50 UNITS " 25 sq. in. = \$

TIME { 10 UNITS TOTAL SHOP TIME = 3.0 HRS.
 50 UNITS " " " = 15.0 HRS.

BEARING 2 EACH/UNIT

BLANK SIZE = $\frac{1}{2}$ DIA X $\frac{1}{2}$ LONG BRASS ROD

MAT'L { 10 UNITS REQUIRES 5 in. = \$
 50 UNITS " 25 in. = \$

TIME { 10 UNITS TOTAL SHOP TIME = 7.0 HRS.
 50 UNITS " " " = 35.0 HRS.

BEARING BLOCK 2 EACH REQD/UNIT

BLANK SIZE = $\frac{1}{4} \times \frac{1}{2} \times \frac{9}{16}$ LONG BRASS

MATERIAL	10 UNITS	REQUIRES	$12 \text{ in of } \frac{1}{4} \times \frac{1}{2} \text{ MATER.} = \$$
	50 UNITS	"	$60 \text{ in } " " " = \$$

TIME	10 UNITS	TOTAL SHOP TIME	= 10 HRS.
	50 UNITS	"	"

CAM SHAFT 2 EACH REQD/UNIT

BLANK SIZE = $\frac{3}{8} \text{ DIA} \times \frac{1}{8} \text{ LONG BRASS ROD}$

MATERIAL	10 UNITS	REQUIRES	$28 \text{ in of } \frac{3}{8} \text{ DIA ROD} = \$$
	50 UNITS	"	$12 \text{ ft. of } " " " = \$$

TIME	10 UNITS	TOTAL SHOP TIME	= 11.0 HRS
	50 UNITS	"	"

SPRING LOAD BLOCK 2 EACH REQD/UNIT

BLANK SIZE = $\frac{3}{8} \times \frac{3}{8} \times \frac{9}{16}$ LONG BRASS

MATERIAL	10 UNITS	REQUIRES	$12 \text{ in of } \frac{3}{8} \times \frac{3}{8} \text{ STOCK} = \$$
	50 UNITS	"	$57 \text{ in } " " " = \$$

TIME	10 UNITS	TOTAL SHOP TIME	= 7.0 HRS.
	50 UNITS	"	"

Cam 2 EACH REQD/UNIT

BLANK SIZE = $\frac{3}{4} \text{ DIA} \times \frac{5}{16} \text{ LONG BRASS ROD}$

MATERIAL	10 UNITS	REQUIRES	$6\frac{1}{2} \text{ in of } \frac{3}{4} \text{ DIA STOCK} = \$$
	50 UNITS	"	$32 \text{ in } " " " = \$$

TIME	10 UNITS	TOTAL SHOP TIME	= 10.0 HRS
	50 UNITS	"	"

This document contains neither recommendations nor conclusions of the Central Intelligence Agency. It should not be distributed outside the CIA without prior approval of the Director of Central Intelligence.

SUPPORT 1 REQD/UNIT

BLANK SIZE = $2\frac{3}{8} \times \frac{5}{8} \times \frac{1}{8}$ THICK BLACK FABRIC PHENOLIC

MAT'L { 10 UNITS REQUIRES 15 sq. in. = \$

50 UNITS " 75 sq. in. = \$

TIME { 10 UNITS TOTAL SHOP TIME = 10.0 HRS

50 UNITS " " " = 50.0 HRS

SUPPORT POST 1 REQD/UNIT

BLANK SIZE = $\frac{3}{4}$ DIA X $1\frac{3}{8}$ LONG BRASS RODMAT'L { 10 UNITS REQUIRES 14 in of $\frac{3}{4}$ DIA STOCK = \$

50 UNITS " 70 in " " " = \$

TIME { 10 UNITS TOTAL SHOP TIME = 10.0 HRS.

50 UNITS " " " = 50.0 HRS.

SPRING LOAD SCREW 2 EACH REQD/UNIT

BLANK SIZE $\frac{3}{4}$ DIA X $\frac{3}{4}$ LONG BRASS RODMAT'L { 10 UNITS REQUIRES 8 in of $\frac{3}{4}$ DIA STOCK = \$

50 UNITS " 38 in " " " = \$

TIME { 10 UNITS TOTAL SHOP TIME = 10.0 HRS.

50 UNITS " " " = 50.0 HRS.

PAINT + OTHER FINISHING

MAT'L COST FOR 10 UNITS - ?

" " " 50 UNITS : ?

TIME FOR 10 UNITS = 6 HRS

" " 50 UNITS = 16 HRS

This document
 file is kept under automatic
 subject to individual systematic review

ASSEMBLY TIME FOR 10 UNITS = 16 HRS

" " " 50 UNITS = 80 HRS